

# **New study shows tornadoes tend toward higher elevations and cause greater damage moving uphill**

August 27 2013

---



The most severe damage caused by the EF5 tornado that struck Joplin, Mo., on May 22, 2011, occurred on flat terrain or when the tornado was moving uphill.

(Phys.org) —The first field investigations of the effect of terrain elevation changes on tornado path, vortex, strength and damage have yielded valuable information that could help prevent the loss of human life and damage to property in future tornadoes.

Engineering researchers at the University of Arkansas analyzed Google Earth images of the massive 2011 Tuscaloosa, Ala., and Joplin, Mo., [tornadoes](#) and found similarities between the two in behavior and interaction with the terrain. The findings likely apply to all tornadoes.

"We wanted to understand the impact of terrain on damage magnitude and tornado path," said Panneer Selvam, professor of civil engineering. "Information about this interaction is critical. It influences decisions about where and how to build, what kind of structure should work at a given site."

The researchers' analysis led to three major observations about the nature and behavior of tornadoes as they interact with terrain:

- Tornadoes cause greater damage when they travel uphill and less damage as they move downhill.
- Whenever possible, tornadoes tend to climb toward [higher elevations](#) rather than going downhill.
- When a region is surrounded by hills, tornadoes skip or hop over valleys beneath and between these hills, and damage is noticed only on the top of the hills.

For years Selvam has studied the effect of [high winds](#) on structures and developed detailed computer models of tornadoes. He and civil engineering graduate student Nawfal Ahmed used tornado path coordinates from the National Oceanic and Atmospheric Administration and imposed this data on overlaid Google Earth images. They studied the tornadoes' damage in depth by comparing historical images to [aerial photographs](#) taken after the events. Google Earth photographed Tuscaloosa one day after the tornado there. For the Joplin tornado, an aerial photograph was taken on June 7, 16 days after the twister.

In terms of magnitude of damage, the data clearly showed that tornadoes

cause greater damage going uphill and huge damage on high ground or ridges. Damage decreased as the tornadoes moved beyond the crest of a hill and going downhill. While it seems logical, this data contradicted a finding from a previous study in which Selvam and a different student found that a hill can act as a protection wall for buildings.

The researchers also found that when approaching a geographic intersection, tornadoes climb toward ridges rather than go downhill, which is counterintuitive when one thinks about wind or water seeking the path of least resistance. With both the Joplin and Tuscaloosa tornadoes, there were several locations where the paths changed direction. At each of these locations, or intersections, the tornadoes consistently sought higher ground.

Finally, Selvam and Ahmed discovered that when a region is surrounded by hills, tornadoes tend to maintain a consistent trajectory rather than follow topographical contours. jumping over valleys to hit hilltops and ridges. With both tornadoes, Selvam said, it was clear that all highland areas suffered the most damage.

Occurring less than a month apart, the Tuscaloosa (April 27) and Joplin (May 22) tornadoes are two of the most deadly and expensive natural disasters in recent U.S. history. Tuscaloosa was an EF4, multiple-[vortex](#) tornado that destroyed parts of Tuscaloosa and Birmingham, Ala. The tornado killed 64 people and caused roughly \$2.2 billion in property damage, which, at the time, made it the costliest single tornado in U.S. history. Only a month later, the Joplin tornado, an EF5 with multiple vortices, which damaged or destroyed roughly a third of the city, killed 158 people, injured 1,150 others and caused \$2.8 billion in damage.

The researchers presented their findings at the 12th Americas Conference on Wind Engineering.

Provided by University of Arkansas

Citation: New study shows tornadoes tend toward higher elevations and cause greater damage moving uphill (2013, August 27) retrieved 4 October 2025 from  
<https://phys.org/news/2013-08-tornadoes-tend-higher-elevations-greater.html>

This document is subject to copyright. Apart from any fair dealing for the purpose of private study or research, no part may be reproduced without the written permission. The content is provided for information purposes only.